


Fig. 1



2/24




Fig. 2

3/24




Fig. 3

4/24




Fig. 4






Fig. 11


5
1892






7/24

Fig. 7




8/24

Fig. 8



9/24

Fig. 9



10/24






Fig. 10

11/24



12/24







Fig. 14

13/24



14/24

Fig. 16



15/24

Fig. 17





Fig. 18



16/24





Fig. 20

Fig. 21





Fig. 22

Fig. 23





Fig. 24

Fig. 25

17/24




Fig. 26




Fig. 28




Fig. 31





Fig. 32

18 / 24

Fig. 27



19/24






Fig. 29

Fig. 30



20/24

Fig. 33



21/24

FIG. 34 is a perspective view of the diverter assembly in a first position.





Fig. 35






Fig. 38




Fig. 36




Fig. 37

23/24




Fig. 39

FIG. 39

24/24

